ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
5

Ward Name
Jakkuru

Street ID
W0584, W0582, W1111, W0769, W1123, W1121, W1115, W

Street Name
NA, Madhura Nagar Rd, 1st Main Rd

Significant Landmark
Agrahara Badavane

Segment No.
5/C-W0584/S044827

Total Length (m)
1385.97

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	249.44	77.627916	13.099156	77.628202	13.096919	Agrahara Badavane 18th cross road	Cross road
2	274.88	77.628084	13.099774	77.628482	13.097321	Agrahara Badavane 19th Cross road	Cross road
3	233.50	77.628376	13.099841	77.628675	13.097751	Agrahara Badavane 20th cross road	cross road
4	182.52	77.628668	13.099877	77.628930	13.098248	Agrahara Badavane 21st cross	cross road
5	121.57	77.628942	13.099914	77.629123	13.098829	Agrahara Badavane 22nd cross	cross road
6	87.07	77.629222	13.099980	77.629359	13.099205	Agrahara Badavane 23rd cross	cross road
7	34.61	77.629508	13.100017	77.629558	13.099708	Agrahara Badavane 24th Cross	cross road
8	202.38	77.627854	13.099750	77.629689	13.100083	Agrahara Badavane	1st main

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements drains and covering slabs at Agrahara layout in ward no. 05 Jakkur

Sanctioned Estimated Amount (Rs.)
9995000

Sanctioned Year
2016-17

Year
2016 - 2017

Type of Work
Others

Other Work Type
Solid Block drain and RCC covering slab

Tender
Not a Tender

Work Details
Solid Block drain and RCC covering slab

Job No. / Work Code
005-17-000041

ork Order No.	Work Order Date	Period of Extention
BBMP/EE/BTP/WO/33/2017-18	19/04/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
31/07/2017	31/07/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0584, W0582, W1111, W0769,

eld Inspection Details

Number of Trees	Any Other Information	Name
0		chandrappa h

Date of Inspection	Remarks
18/07/2017	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0584, W0582, W1111, W0769,

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	18/07/2017	17/08/2017	Approved
SE	K.M.Vasu	18/07/2017	17/08/2017	Verified
EE	H.T.Mohandas	18/07/2017	17/08/2017	Verified
AEE	Sridhar B.S	18/07/2017	17/08/2017	Verified
AE	Chandrappa H	18/07/2017	17/08/2017	Mobile verification done
AE	Chandrappa H	18/07/2017	17/08/2017	Forward

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0584, W0582, W1111, W0769,